

Professional Compression Crimping Tool



Features

- Connects RG-59 and RG-6 F compression connectors on coaxial cables.
- Permanent and best quality connection.
- Insert the correct plunger into the tool's holder and then insert the stripped cable into the connector, make sure the cable is inserted to the end.
- Place connector with cable into the tool's holder.
- Squeeze handles.
- Remove the crimped connector from the tool

Model	Compressed distance	Crimping connector
HY-5085C1	19.30+0.15mm	RG-59(4C),RG-6(5C) For crimping F connecto
HY-5085C2	20.30+0.15mm	
HY-5085C3	21.00+0.15mm	

